



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Report Date: September 19, 2006

Supervisor DAH

**Mine Name:** Long Gulch II  
**Operator Name:** Mike Dettamanti  
P.O. Box 291  
Kanab, Utah 84741

**Permit number:** S/017/039  
**Inspection Date:** September 11, 2006  
**Time:** 1:45 PM

**Inspector(s):** Doug Jensen  
**Other Participants:** None  
**Mine Status:** Abandoned

**Weather:** Clear, warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

The operator forfeited this site due to non-payment of fees.

#### Directions to Site:

See GIS map in file.

#### Inspection Summary:

Vegetation has begun to grow on the site and the access road has begun to fill in with vegetation. As this site has been taken over by the BLM the operator has no further reclamation responsibilities.

#### Conclusions and Recommendations:

The Kanab FO has agreed with the Division that this permit should be closed. A document will be prepared closing the permit.

**Inspector's Signature**

Doug Jensen

**Date:**

9/20/06

dj:pb

cc:

Mike Dettamanti

Doug Powell, BLM, Kanab FO UTU-72768

O:\M017-Garfield\S0170039-LongGulch\Inspections\09112006insp.doc



